



PPS | POWER PLANT
SERVICES

Automatic Welding Capabilities

Welding Service Examples

- Turbine casing crack repair & design modification
- Valve seats & rib refurbishment
- Steam Chest nozzle repair
- Snout pipe restoration
- Piping repair or installation
- On-site welding capabilities
- Automatic, manual, semi-manual processes

Welding Inspections

- NDE (Nondestructive Testing)
- Ultrasonic Testing (UT)
- Radiography
- Hardness Testing.
- X-rays are utilized throughout to check for weld deposit integrity.

Welding Types

Shield Metal Arc | Gas Metal Arc | Gas Tungsten Arc | Plasma Transfer Arc
| Submerged Arc | Manual, Automatic & Robotic



PPS | POWER PLANT
SERVICES

Sales@ppsvcs.com

(708)345-8600

WWW.PPSVCS.COM